


**Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam**  
**SUPPLIER LASER DIODE STACKS 808nm**

**WATER FOUND INSIDE LASER MODULE, REPLACEMENT  
RECOMMENDED**



Water found inside laser module, replacement recommended Read [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM) for diode stack tech and cosmetic device knowledge



+7(918)0110234 offers support for cosmetic laser service problems