


**THERE IS MOISTURE INSIDE THE LASER MODULE - REPLACE THE
MODULE**



There is moisture inside the laser module - replace the module WWW.ROMSHI.COM shares
experience-based knowledge on 808nm diode stacks and laser fixes



Buy diode stacks from +7(918)0110234 on WhatsApp or Telegram