

LASER MODULE NEEDS REPLACEMENT DUE TO WATER INSIDE



Laser module needs replacement due to water inside WWW.ROMSHI.COM is your source for
808nm diode stacks and laser repair how-tos



+7(918)0110234 (WhatsApp, Telegram) sells high-quality diode
stacks