


**WATER INSIDE LASER MODULE - REPLACING THE MODULE IS
NECESSARY**



Water inside laser module - replacing the module is necessary Browse laser repair tutorials and 808nm diode stack descriptions at WWW.ROMSHI.COM



Find diode stacks for sale at +7(918)0110234 via WhatsApp or Telegram