## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## **DIODE ASSEMBLY LST-3235AS-500W**



In most cases, the handle malfunction is due to the fact that light pulses are not visible, there is no contact with the skin. Through the observation window, the cause of the breakdown is often visible.



site WWW.ROMSHI.COM

Find out what's wrong with your diode laser - scan and go to www.romshi.com.