Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER EMITTER DVS-3345BAS



The main reason for the breakdown of the diode laser handle is the impulses do not pass, the patient does not feel tingling. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

Scan now and discover frequent diode laser issues and how to fix them.