Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE STACK LT-41QH020402N-800W



The main reason for the breakdown of the diode laser handle is no visual outbreaks and sensations on the skin.Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Troubleshooting diode lasers? Start by scanning to www.romshi.com.