

LASER EMITTER LT-14CH020802N-1200W



A common breakdown of the handle is that there are no light impulses, there is no contact with the skin. Through the observation window, the cause of the breakdown is often visible.



Laser no longer effective? The diode stack is a common issue. Scan the QR to visit www.romshi.com for support.

site WWW.ROMSHI.COM