Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER EMITTER LT-41QH02030203N-1000W



One of the typical problems of the diode laser is that the laser does not work, and the sensations disappear. Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Laser not removing hair like it used to? It could be the diode stack.

Scan the QR code to access repair guides and parts at www.romshi.com.