Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT



LASER BAR LSR-1006AI

The main defect in the work of the diode handle is that the impulses do not pass, the patient does not feel tingling. When examining through the window, you can notice a malfunction.



site WWW.ROMSHI.COM

If your laser hair removal tool isn't performing properly, the diode stack might be faulty. Scan the QR code to learn more at www.romshi.com.