Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER BAR MKJ-72501202



One of the typical problems of the diode laser is that the laser does not work, and the sensations disappear. Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Laser no longer effective? The diode stack is a common issue. Scan the QR to visit www.romshi.com for support.