Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX LST-3334AS



The main reason for the breakdown of the diode laser handle is no light pulses, there is no contact with the skin. Through the observation window, the cause of the breakdown is often visible.



site WWW.ROMSHI.COM

Laser equipment not functioning? Scan the QR code and discover repair resources on www.romshi.com.