Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY HD-8A60-600W



The main defect in the work of the diode handle is that the laser does not work, and the sensations disappear. Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Access laser repair instructions and parts suggestions with one scan to www.romshi.com.