## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## **LASER EMITTER HD-82A0-1000W**



Frequent malfunction of the laser handle - no light impulses are visible, there is no contact with the skin. Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Laser device not effective? The diode stack could be the issue.

Scan for repair info on www.romshi.com.