Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER BAR J-01AD205-A22276-GX



A common breakdown of the handle is that the outbreaks do not occur, there is no tingling either. Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Loss of power in your laser hair remover? Scan the QR to troubleshoot at www.romshi.com.