Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT



DIODE MATRIX 202309012943

The most common problem with the diode laser handle is not visible light impulses, there is no contact with the skin.Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Issues with hair removal? Your laser may have a bad diode stack. Scan QR to access www.romshi.com.