Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER BAR GTHM-500



A common breakdown of the handle is that there is a loss of flashes and sensations. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

If your laser isn't functioning, the QR code leads to www.romshi.com for repair and parts.