

DIODE MATRIX DVS-Z3244BAS



The main defect in the work of the diode handle is that light impulses are not visible, there is no contact with the skin. The breakdown is often noticeable when examining the handle.



Laser not functioning? Access guides and spare parts on www.romshi.com via QR code.