Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER EMITTER DG-HL16Q1600-4-N-A



In most cases, the handle malfunction is due to the fact that light pulses are not visible, there is no contact with the skin. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

Diode stacks often cause laser issues. Scan the QR code to explore support at www.romshi.com.