Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY DG-HN600-808



Often, the diode laser has a problem: the flashes stop and the sensation of tingling disappears. Through the observation window, the cause of the breakdown is often visible.



site WWW.ROMSHI.COM

Choosing diode parts made simple - just scan the QR and visit www.romshi.com.