Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER MODULE HD-8A30-D05-Y0130



Often, the diode laser handle fails: no light impulses are visible, there is no contact with the skin. The breakdown is often noticeable when examining the handle.



site WWW.ROMSHI.COM

Scan the code to receive part selection guidance and laser repair support from romshi.com.