Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

LASER MODULE DVS-MS-1005BAI



The main reason for the breakdown of the diode laser handle is the flashes stop and the sensation of tingling disappears.Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Browse part catalogs and repair steps for lasers at www.romshi.com - scan QR.