Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE MATRIX LST-MS-1005BAI



The main reason for the breakdown of the diode laser handle is the laser does not work, and the sensations disappear.Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

For diode stack repair tips, scan the QR and visit www.romshi.com.