


DIODE ASSEMBLY LST-MS-1012BAI



Dot in the work of the diode laser handle is expressed as follows: flashes disappear and there is no tingling. The handle defect is often visually observed through the window.



Scan to unlock knowledge on diode laser components and fixes from romshi.com.