


## DIODE STACK DVS-1016AI



The main defect in the work of the diode handle is that light impulses are not visible, there is no contact with the skin. Damage can be detected visually through the transparent part of the handle.



Scan now for diode part guides and troubleshooting tools on [romshi.com](http://romshi.com).