## Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## **DIODE MATRIX LST-1005AI**



In most cases, the handle malfunction is due to the fact that the laser does not work, and the sensations disappear. Through the observation window, the cause of the breakdown is often visible.



site WWW.ROMSHI.COM

Trouble with laser equipment? Scan and discover fixes at www.romshi.com.