Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE STACK LST-1012AI



One of the typical problems of the diode laser is that the outbreaks do not occur, there is no tingling either. Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Diode spare part confusion? Get clarity from romshi.com by scanning QR.