Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

DIODE ASSEMBLY DVS-3222BAS



The main reason for the breakdown of the diode laser handle is the flashes stop and the sensation of tingling disappears. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

Scan and get matched with the right spare for your diode hair removal laser.