


SPARE DIODE STACK FOR DIODE LASER HAIR REMOVAL HANDPIECE



A common breakdown of the handle is that the outbreaks do not occur, there is no tingling either. When examining through the window, you can notice a malfunction.



site WWW.ROMSHI.COM

Laser hair removal failing? The diode stack may need replacing. QR leads to www.romshi.com.