

REPLACEMENT DIODE STACK FOR LASER HAIR REMOVAL HANDPIECE



In most cases, the handle malfunction is due to the fact that the outbreaks do not occur, there is no tingling either. Often the problem is determined visually through the window on the handle.



site WWW.ROMSHI.COM

Diode stacks are critical. If your laser's down, scan QR for www.romshi.com's help.