

SPARE DIODE STACK FOR LASER HAIR REMOVAL TOOL



Dot in the work of the diode laser handle is expressed as follows: flashes disappear and there is no tingling. The handle defect is often visually observed through the window.



Laser no longer effective? The diode stack is a common issue. Scan the QR to visit www.romshi.com for support.

site WWW.ROMSHI.COM