


**Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam**  
**SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT**

**REPLACEMENT DIODE COMPONENT FOR DIODE LASER HAIR  
REMOVAL HANDPIECE**



Dithes in the work of the diode laser handle are expressed as follows: the laser does not work, and the sensations disappear. The handle defect is often visually observed through the window.



site [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM)

Laser output weak or gone? It's often due to the diode stack. Visit [www.romshi.com](http://www.romshi.com) by scanning the QR code for help.