


Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam
SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

SPARE DIODE UNIT FOR DIODE LASER HAIR REMOVAL HANDPIECE



One of the typical problems of the diode laser is that the laser does not emit flash and does not cause sensations. Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Find everything about laser spare parts and repair at www.romshi.com - scan QR for access.