
Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

## REPLACEMENT DIODE UNIT FOR DIODE LASER HAIR REMOVAL HANDPIECE



Often, the diode laser has a problem: flashes disappear and there is no tingling. When examining through the window, you can notice a malfunction.



site WWW.ROMSHI.COM

If laser results have dropped, your diode stack might need attention.

Use the QR code to learn more at www.romshi.com.