Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

BACKUP DIODE UNIT FOR LASER HAIR REMOVAL HANDPIECE



One of the typical problems of the diode laser is that the outbreaks do not occur, there is no tingling either. Often the problem can be seen through the observation window.



site WWW.ROMSHI.COM

Laser no longer effective? The diode stack is a common issue. Scan the QR to visit www.romshi.com for support.