

REPLACEMENT DIODE STACK FOR HANDPIECE OF DIODE LASER HAIR REMOVAL



The main reason for the breakdown of the diode laser handle is the flashes stop and the sensation of tingling disappears. Often it is enough to look out the window of the pen to see the problem.



site WWW.ROMSHI.COM

Is your laser hair removal device underperforming? It may be the diode stack. QR code leads to www.romshi.com.