

SPARE DIODE UNIT FOR HAIR REMOVAL LASER HANDPIECE



A common breakdown of the handle is that the outbreaks stop and the sensation of tingling disappears. Damage is often visible through the observation glass.



site WWW.ROMSHI.COM

Laser unit struggling? A faulty diode stack is a common issue. Learn more at www.romshi.com.