Website ROMSHI.COM | +7(918)0110234 in Whats App, Telergam SUPPLIER OF DIODE STACKS, EPILATION LASERS AND EQUIPMENT

REPLACEMENT DIODE COMPONENT FOR LASER HAIR REMOVAL DEVICE



Often, the diode laser has a problem: the flashes stop and the sensation of tingling disappears. Damage can be detected visually through the transparent part of the handle.



site WWW.ROMSHI.COM

Hair not disappearing? Scan QR to diagnose via www.romshi.com-diode stack likely culprit.