


REPLACEMENT DIODE LASER STACK FOR HAIR REMOVAL HAND TOOL



The main defect in the work of the diode handle is that the outbreaks do not occur, there is no tingling either. Sometimes it can be recognized visually by looking out the window.



site WWW.ROMSHI.COM

Hair laser no longer working properly? A common issue is the diode stack. Scan the QR and go to www.romshi.com for solutions.