


SUBSTITUTE DIODE COMPONENT FOR DIODE LASER HAIR REMOVAL HANDPIECE



Often, the diode laser handle fails: flashes do not occur, there is no tingling either. The handle defect is often visually observed through the window.



site WWW.ROMSHI.COM

Find which diode part your laser needs at www.romshi.com - scan to check.