


SPARE DIODE STACK FOR HAIR REMOVAL LASER EQUIPMENT



The most common problem with the diode laser handle is the laser does not emit flash and does not cause sensations. Often the problem is determined visually through the window on the handle.



Hair not being removed as expected? Learn about diode stack solutions at www.romshi.com via QR.

site WWW.ROMSHI.COM