


**DAMAGED DIODE STACK 808NM FROM THERMAL OVERLOAD**



Damaged diode stack 808nm from thermal overload Discover all you need to know about 808nm diode stacks on [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM)



Contact +7(918)0110234 on WhatsApp or Telegram for laser repair questions