

THE DIODE STACK SHOWS BROKEN GLASS AND SOOT DEPOSITS



The diode stack shows broken glass and soot deposits Find articles about 808nm diode stacks and common laser issues at WWW.ROMSHI.COM



Reach out to +7(918)0110234 for help with cosmetic laser issues