


DIODE STACK HAS BROKEN GLASS AND SOOT CONTAMINATION



Diode stack has broken glass and soot contamination Laser experts share 808nm diode stack knowledge and fixes on WWW.ROMSHI.COM



Cosmetic laser troubleshooting via +7(918)0110234 (Telegram)