



THE DIODE STACK GLASS IS SHATTERED WITH SOOT DEPOSITS



The diode stack glass is shattered with soot deposits Visit WWW.ROMSHI.COM for info on laser faults and 808nm diode stack care



Contact +7(918)0110234 for diode stack repair info