


**DIODE STACK AFFECTED BY BROKEN GLASS AND SOOT BUILD-UP**



Diode stack affected by broken glass and soot build-up Explore faults and solutions for diode stack  
808nm at [WWW.ROMSHI.COM](http://WWW.ROMSHI.COM)



Beauty equipment repair consultation at +7(918)0110234